






报告编号	结论	报告日期	影像资料
DAJC-7F01101-2022	综合判定该提升机合格	2022-11-8	
DAJC-7F01105-2022	合格	2022-11-9	
DAJC-7F01112-2022	综合判定该提升机合格	2022-12-2	

报告编号	结论	报告日期	影像资料
DAJC-7F01113-2022	综合判定该提升机合格	2022-12-4	
DAJC-7F01115-2022	综合判定该提升机合格	2022-12-13	
DAJC-7F01118~119-2022	综合判定该提升机合格	2022-12-12	

报告编号	结论	报告日期	影像资料
DAJC-7F02083-2022	综合判定该提升机合格	2022-12-4	
DAJC-7F03100~101-2022	综合判定该提升绞车合格	2022-11-15	
DAJC-7F04222-2022	综合判定该防坠器合格	2022-11-21	



报告编号	结论	报告日期	影像资料
DAJC-7F04223~224-2022	综合判定该防坠器合格	2022-11-22	
DAJC-7F04226~227-2022	综合判定该防坠器合格	2022-12-15	


报告编号	结论	报告日期	影像资料
DAJC-7F05137-2022	合格	2022-11-3	
DAJC-7F05142-2022	合格	2022-11-21	


报告编号	结论	报告日期	影像资料
DAJC-7F05143~144-2022	合格	2022-11-22	
DAJC-7F05145~146-2022	合格	2022-12-15	
DAJC-7F10500-2022	符合标准要求	2022-11-3	


报告编号	结论	报告日期	影像资料
DAJC-7F10505~506-2022	判定合格	2022-11-7	
DAJC-7F10507~509-2022	判定合格	2022-11-7	
DAJC-7F10511-2022	符合标准要求	2022-11-8	


报告编号	结论	报告日期	影像资料
DAJC-7F10512~514-2022	符合标准要求	2022-11-8	 位置: 119.999079 纬度: 37.416944 地址: 山东省烟台市莱州市莱州港 莱州市莱州港有限公司(南门) 时间: 2022-11-08 10:39:32 电话: 178990784 电话: 17477308 地址: 山东省烟台市莱州市莱州港 莱州市莱州港有限公司(南门) 时间: 2022-11-08 10:39:30
DAJC-7F10523-2022	符合标准要求	2022-11-9	 位置: 120.942481 纬度: 37.320938 地址: 山东省烟台市莱州市莱州港 莱州市莱州港有限公司(南门) 时间: 2022-11-09 16:01:05 电话: 178990784 电话: 17477308 地址: 山东省烟台市莱州市莱州港 莱州市莱州港有限公司(南门) 时间: 2022-11-09 16:01:05 电话: 178990784 电话: 17477308
DAJC-7F10524~525-2022	符合标准要求	2022-11-12	 位置: 120.942481 纬度: 37.320938 地址: 山东省烟台市莱州市莱州港 莱州市莱州港有限公司(南门) 时间: 2022-11-12 14:28:54 电话: 178990784 电话: 17477308 地址: 山东省烟台市莱州市莱州港 莱州市莱州港有限公司(南门) 时间: 2022-11-12 14:28:54 电话: 178990784 电话: 17477308


报告编号	结论	报告日期	影像资料
DAJC-7F10526~527-2022	符合标准要求	2022-11-15	
DAJC-7F10528-2022	符合标准要求	2022-11-21	
DAJC-7F10529-2022	符合标准要求	2022-11-22	



报告编号	结论	报告日期	影像资料
DAJC-7F10533-2022	符合标准要求	2022-12-6	
DAJC-7F10534-2022	符合标准要求	2022-12-8	
DAJC-7F10539-2022	符合标准要求	2022-12-8	

报告编号	结论	报告日期	影像资料
DAJC-7F10540~541-2022	符合标准要求	2022-12-11	
DAJC-7F10543-2022	符合标准要求	2022-12-14	
DAJC-7F10544-2022	符合标准要求	2022-12-14	



报告编号	结论	报告日期	影像资料
DAJC-7F10545~546-2022	符合标准要求	2022-12-14	
DAJC-7F10548-2022	符合标准要求	2022-12-17	
DAJC-7F10549-2022	符合标准要求	2022-12-17	

报告编号	结论	报告日期	影像资料
DAJC-7F10555~563-2022	符合标准要求	2022-12-21	
DAJC-7F11106~110-2022	综合判定该空气压缩机合格	2022-3-13	
DAJC-7F11496-2022	综合判定该空气压缩机合格	2022-11-14	


报告编号	结论	报告日期	影像资料
DAJC-7F11523~527-2022	综合判定该空气压缩机合格	2022-12-4	
DAJC-7F11533~534-2022	综合判定该空气压缩机合格	2022-12-10	
DAJC-7F11535~538-2022	综合判定该空气压缩机不合格	2022-12-14	


报告编号	结论	报告日期	影像资料
DAJC-7F11551~553-2022	综合判定该空气压缩机合格	2022-12-21	 经度: 118.506806 纬度: 31.459762 地址: 安徽省马鞍山市当涂县015号 道龙门 时间: 2022-12-21 09:56:56 经度: 118.506744 纬度: 31.459750 地址: 安徽省马鞍山市当涂县015号 道龙门 时间: 2022-12-21 09:56:15
DAJC-7F12146-2022	综合判定该主排水系统合格	2022-12-3	
DAJC-7F12147-2022	综合判定该主排水系统合格	2022-12-13	

报告编号	结论	报告日期	影像资料
DAJC-7F12148-2022	综合判定该主排水系统合格	2022-12-14	 
DAJC-7F12149-2022	综合判定该主排水系统合格	2022-12-14	 
DAJC-7F13697-2022	综合判定该泵房所检水泵合格	2022-11-9	 

报告编号	结论	报告日期	影像资料
DAJC-7F13721~724-2022	综合判定该泵房所检水泵合格	2022-12-3	
DAJC-7F13725~727-2022	综合判定该泵房所检水泵合格	2022-12-13	


报告编号	结论	报告日期	影像资料
DAJC-7F13730~731-2022	综合判定该泵房所检水泵合格	2022-12-10	 经度: 120.129470 纬度: 37.400598 地址: 山东省烟台市莱州市206国道 金都建材 时间: 2022-12-10 07:59:04
DAJC-7F13732~739-2022	综合判定该泵房所检水泵合格	2022-12-14	

报告编号	结论	报告日期	影像资料
DAJC-7F13764~768-2022	综合判定该泵房所检水泵合格	2022-12-14	
DAJC-7F143688~3689-2022	合格	2022-11-8	
DAJC-7F143728~3736-2022	合格	2022-11-15	

报告编号	结论	报告日期	影像资料
DAJC-7F143784~3792-2022	合格	2022-12-3	 经纬度: 116.449666 纬度: 36.079659 地址: 山东省泰安市东平县326省道宋庙村 时间: 2022-12-03 14:47:50 海拔: 37.6米 天气: 6~6℃ 东风 备注: 长按水印编辑备注 经纬度: 116.449818 纬度: 36.076480 地址: 山东省泰安市东平县326省道宋庙村 时间: 2022-12-03 14:14:24 海拔: 25.1米 天气: 6~6℃ 东风 备注: 长按水印编辑备注
DAJC-7F143793~3796-2022	合格	2022-12-4	 经纬度: 116.449666 纬度: 36.079659 地址: 山东省泰安市东平县326省道宋庙村 时间: 2022-12-04 14:47:50 海拔: 37.6米 天气: 6~6℃ 东风 备注: 长按水印编辑备注 经纬度: 116.449818 纬度: 36.076480 地址: 山东省泰安市东平县326省道宋庙村 时间: 2022-12-04 14:14:24 海拔: 25.1米 天气: 6~6℃ 东风 备注: 长按水印编辑备注
DAJC-7F143797~3802-2022	合格	2022-12-6	 经纬度: 116.449666 纬度: 36.079659 地址: 山东省泰安市东平县326省道宋庙村 时间: 2022-12-06 14:47:50 海拔: 37.6米 天气: 6~6℃ 东风 备注: 长按水印编辑备注 经纬度: 116.449818 纬度: 36.076480 地址: 山东省泰安市东平县326省道宋庙村 时间: 2022-12-06 14:14:24 海拔: 25.1米 天气: 6~6℃ 东风 备注: 长按水印编辑备注



报告编号	结论	报告日期	影像资料
DAJC-7F143803~3808-2022	合格	2022-12-7	
DAJC-7F143809~3810-2022	合格	2022-12-6	
DAJC-7F143811~3828-2022	合格	2022-12-5	




报告编号	结论	报告日期	影像资料
DAJC-7F143829~3831-2022	合格	2022-12-7	
DAJC-7F143832~3849-2022	合格	2022-12-5	
DAJC-7F143850~3856-2022	合格	2022-12-6	


报告编号	结论	报告日期	影像资料
DAJC-7F143917~3924-2022	合格	2022-12-3	
DAJC-7F143925-2022	合格	2022-12-4	
DAJC-7F143926~3927-2022	合格	2022-12-4	


报告编号	结论	报告日期	影像资料
DAJC-7F151108-2022	合格	2022-11-7	
DAJC-7F151109-2022	合格	2022-11-7	
DAJC-7F151147~1148-2022	合格	2022-11-15	

报告编号	结论	报告日期	影像资料
DAJC-7F151158~1165-2022	合格	2022-11-23	
DAJC-7F151166-2022	合格	2022-12-4	


报告编号	结论	报告日期	影像资料
DAJC-7F151167~1168-2022	合格	2022-12-7	 地点: 116.415525 纬度: 35.545547 地址: 山东省泰安市泰山区 平度市平度市平度市 日期: 2022-12-07 10:55 海拔: 58.5m 天气: 晴 备注: 0.5m 仰角拍摄
DAJC-7F151169-2022	合格	2022-12-3	
DAJC-7F151170~1172-2022	合格	2022-12-7	

报告编号	结论	报告日期	影像资料
DAJC-7F151173-2022	合格	2022-12-3	
DAJC-7F151174~1175-2022	合格	2022-12-5	
DAJC-7F151176~1178-2022	合格	2022-12-6	

报告编号	结论	报告日期	影像资料
DAJC-7F151198-2022	合格	2022-12-13	
DAJC-7F151199~1200-2022	合格	2022-12-16	
DAJC-7F151201-2022	合格	2022-12-4	

报告编号	结论	报告日期	影像资料
DAJC-7F151202-2022	合格	2022-12-6	
DAJC-7F161188~1190-2022	合格	2022-11-15	
DAJC-7F161195~1212-2022	合格	2022-11-16	


报告编号	结论	报告日期	影像资料
DAJC-7F161213~1230-2022	合格	2022-11-17	 经纬度: 120.131639 纬度: 37.402446 地址: 山东省烟台市莱州市228国道 金都建材 时间: 2022-11-17 08:34:42 经纬度: 120.131604 纬度: 37.402483 地址: 山东省烟台市莱州市228国道 金都建材 时间: 2022-11-17 08:35:18
DAJC-7F161233~1234-2022	合格	2022-11-24	 经纬度: 120.098408 纬度: 37.388572 地址: 山东省烟台市莱州市官庄路 莱州汇金矿业投资有限公司砂金 矿项目部 时间: 2022-11-24 08:22:41 经纬度: 120.094020 纬度: 37.388877 地址: 山东省烟台市莱州市官庄路 莱州汇金矿业投资有限公司砂金 矿项目部 时间: 2022-11-24 08:28:21
DAJC-7F161235~1245-2022	合格	2022-12-3	 经纬度: 116.455272 纬度: 35.876583 地址: 山东省泰安市东平县105国道51号 时间: 2022-12-03 15:04:18 经纬度: 116.455249 纬度: 35.876571 地址: 山东省泰安市东平县105国道51号 时间: 2022-12-03 15:05:07

报告编号	结论	报告日期	影像资料
DAJC-7F161246~1257-2022	合格	2022-12-5	
DAJC-7F161262~1275-2022	合格	2022-12-20	/
DAJC-7F161276~1299-2022	合格	2022-12-19	 经度: 120.131657 纬度: 37.402415 地址: 山东省烟台市莱州市228国道金都建材 时间: 2022-12-19 12:25:22 海拔: 52.9米 天气: 3~4℃ 北风 备注: 长坡水印编辑备注 经度: 120.137109 纬度: 37.403484 地址: 山东省烟台市莱州市金基建材 时间: 2022-12-19 12:47:26

报告编号	结论	报告日期	影像资料
DAJC-7F161300~1305-2022	合格	2022-12-21	 经纬: 120.729705 高程: 37.400336 地址: 山东省烟台莱州市206国道金岭 227 时间: 2022-12-21 16:20:24 海拔: 32.4米 天气: 晴 4~6℃ 北风 备注: 长镜头拍摄备注 经纬: 120.729705 高程: 37.400336 地址: 山东省烟台莱州市206国道金岭 227 时间: 2022-12-21 16:20:24 海拔: 32.4米 天气: 晴 4~6℃ 北风 备注: 长镜头拍摄备注
DAJC-7F161306~1310-2022	合格	2022-12-22	/
DAJC-7F161311~1314-2022	合格	2022-12-21	/
DAJC-7F161315~1316-2022	合格	2022-12-22	 经纬: 120.130916 高程: 37.301926 地址: 山东省烟台莱州市206国道莱州 临矿综合门诊部 时间: 2022-12-22 14:19:50 海拔: 0.0米 天气: 晴 5~9℃ 西南风 备注: 长镜头拍摄备注 经纬: 120.115460 高程: 37.305330 地址: 山东省烟台莱州市228国道莱州 奥康学校 时间: 2022-12-22 14:40:38 海拔: 0.0米 天气: 晴 5~9℃ 西南风 备注: 长镜头拍摄备注

报告编号	结论	报告日期	影像资料
DAJC-7F161317~1320-2022	合格	2022-12-21	 经纬: 120.130047 纬度: 37.400329 地址: 山东省烟台市莱州市206国道金岭 建材 时间: 2022-12-21 12:22:19 海拔: 10.8米 天气: 5-9℃ 西南风 备注: 长隆水和编辑备注 经纬: 120.130285 纬度: 37.400263 地址: 山东省烟台市莱州市206国道金岭 建材 时间: 2022-12-21 12:41:31 海拔: 6.9米 天气: 5-9℃ 西南风 备注: 长隆水和编辑备注
DAJC-7F161321~1322-2022	合格	2022-12-22	 经纬: 120.129817 纬度: 37.400351 地址: 山东省烟台市莱州市206国道金岭 建材 时间: 2022-12-22 12:33:08 海拔: 86.0米 天气: 5-9℃ 西南风 备注: 长隆水和编辑备注 经纬: 120.129712 纬度: 37.400450 地址: 山东省烟台市莱州市206国道金岭 建材 时间: 2022-12-22 12:33:41 海拔: 82.8米 天气: 5-9℃ 西南风 备注: 长隆水和编辑备注
DAJC-7F161323~1326-2022	合格	2022-12-6	 经纬: 116.422017 纬度: 36.884469 地址: 山东省烟台市莱州市莱州路6号彭集镇大 牛村小学 时间: 2022-12-06 13:29:10 经纬: 116.422194 纬度: 36.884373 地址: 山东省烟台市莱州市莱州路6号彭集镇大 牛村小学 时间: 2022-12-06 13:27:08

报告编号	结论	报告日期	影像资料
DAJC-7F161327~1334-2022	合格	2022-12-7	
DAJC-7F17176-2022	合格	2022-11-8	


报告编号	结论	报告日期	影像资料
DAJC-7F17177~178-2022	合格	2022-11-24	 电话: 120 093608 手机: 37-388572 地址: 山东省烟台市莱州市吕村路 莱州汇金矿业有限公司砂金 项目目标 时间: 2022-11-24 08:12:22 电话: 120 094008 手机: 37-388750 地址: 山东省烟台市莱州市吕村路 莱州汇金矿业有限公司砂金 项目目标 时间: 2022-11-24 08:19:00
DAJC-7F18007~013-2022	合格	2022-12-21	
DAJC-7F22655~657-2022	合格	2022-11-18	 电话: 120 09249 手机: 37-388562 地址: 山东省烟台市莱州市吕村路 莱州汇金矿业有限公司砂金 项目目标 时间: 2022-11-18 08:30:44 电话: 120 09249 手机: 37-388562 地址: 山东省烟台市莱州市吕村路 莱州汇金矿业有限公司砂金 项目目标 时间: 2022-11-18 08:33:00



报告编号	结论	报告日期	影像资料
DAJC-7F22658~664-2022	合格	2022-12-5	 经度: 116.442337 纬度: 35.886005 地址: 山东省泰安市东平县幸福路6号东平宏达厂(东北门) 时间: 2022-12-05 14:40:42
DAJC-7F22665~667-2022	合格	2022-12-3	 经度: 116.449663 纬度: 35.896435 地址: 山东省泰安市东平县彭集街道姜庙村 时间: 2022-12-03 15:10:41 海拔: 50.9米 天气: 6~6℃ 东风 备注: 长流水印像请备注  经度: 116.447661 纬度: 35.876637 地址: 山东省泰安市东平县彭集街道姜庙村 时间: 2022-12-03 15:10:57 海拔: 48.9米 天气: 6~6℃ 东风 备注: 长流水印像请备注


报告编号	结论	报告日期	影像资料
DAJC-7F23252-2022	所检钢丝绳符合 MT/T970-2005 要求	2022-11-12	
DAJC-7F23253-2022	所检试件合格	2022-11-13	
DAJC-7F23256-2022	所检试件合格	2022-11-16	

报告编号	结论	报告日期	影像资料
DAJC-7F23263~264-2022	所检试件合格	2022-11-16	
DAJC-7F23265-2022	所检试件合格	2022-11-17	
DAJC-7F23273-2022	所检试件合格	2022-11-18	



报告编号	结论	报告日期	影像资料
DAJC-7F23274-2022	所检试件合格	2022-11-15	
DAJC-7F23275-2022	所检试件合格	2022-11-19	


报告编号	结论	报告日期	影像资料
DAJC-7F23312~313-2022	所检试件合格	2022-12-2	
DAJC-7F23316-2022	所检试件合格	2022-12-9	
DAJC-7F23317~318-2022	所检试件合格	2022-12-11	

报告编号	结论	报告日期	影像资料
DAJC-7F23319-2022	所检试件合格	2022-12-17	
DAJC-7F24089-2022	合格	2022-12-3~7	
DAJC-7F33031~038-2022	部分项目不合格	2022-12-7	


报告编号	结论	报告日期	影像资料
DAJC-7F33039~043-2022	部分项目不合格	2022-12-8	
DAJC-7F33060~067-2022	部分项目不合格	2022-12-10	/
DAJC-7F50056~061-2022	综合判定该空气压缩机合格	2022-11-14	
DAJC-7F61211-2022	所检钢丝绳符合 MT/T970-2005 要求	2022-11-15	



报告编号	结论	报告日期	影像资料
DAJC-7F61222~226-2022	所检钢丝绳符合 MT/T970-2005 要求	2022-11-15	
DAJC-7F61239-2022	所检钢丝绳符合 MT/T970-2005 要求	2022-11-23	




报告编号	结论	报告日期	影像资料
DAJC-7F61240-2022	所检钢丝绳符合 MT/T970-2005 要求	2022-11-21	
DAJC-7F61241-2022	所检钢丝绳符合 MT/T970-2020 要求	2022-11-19	
DAJC-7F61242-2022	所检钢丝绳符合 MT/T970-2005 要求	2022-11-18	



报告编号	结论	报告日期	影像资料
DAJC-7F61243~245-2022	所检钢丝绳符合 MT/T970-2005 要求	2022-11-20	 经纬度: 119.940666 纬度: 37.390371 地址: 山东省烟台市莱州市永福路 金水苑 时间: 2022-11-20 00:43:50 经纬度: 119.940152 纬度: 37.390457 地址: 山东省烟台市莱州市金仓街 道新立金矿提升公司 时间: 2022-11-20 08:30:15
DAJC-7F61246~248-2022	所检钢丝绳符合 MT/T970-2005 要求	2022-11-21	 经纬度: 119.945658 纬度: 37.390111 地址: 山东省烟台市莱州市金水苑 时间: 2022-11-21 09:49:56 海拔: 3.0 米 经纬度: 119.952157 纬度: 37.386362 地址: 山东省烟台市莱州市金沙路119 号凤凰岭村 时间: 2022-11-21 08:42:23 海拔: 4.0 米
DAJC-7F61251-2022	所检钢丝绳符合 MT/T970-2005 要求	2022-11-20	 经纬度: 119.940666 纬度: 37.390371 地址: 山东省烟台市莱州市永福路 金水苑 时间: 2022-11-20 00:43:50


报告编号	结论	报告日期	影像资料
DAJC-7F61252-2022	所检钢丝绳符合 MT/T970-2005 要求	2022-12-8	 
DAJC-7F61254-2022	所检钢丝绳符合 MT/T970-2005 要求	2022-12-10	 
DAJC-7F69198~199-2022	合格	2022-12-11	 





报告编号	结论	报告日期	影像资料
DAJC-7F69200~201-2022	合格	2022-12-17	
DAJC-7F35020-2022	合格	2022-11-19	/
DAJC-7F36022-2022	合格	2022-10-29	/
DAJC-7F36023-2022	合格	2022-11-19	/
DAJC-7F37038~039-2022	合格	2022-12-20	/
DAJC-7F37040-2022	合格	2022-12-21	/
DAJC-7F37041-2022	合格	2022-12-22	/
DAJC-7F37042-2022	合格	2022-12-23	/
DAJC-7F37043-2022	合格	2022-12-24	/
DAJC-7F37044-2022	合格	2022-12-25	/
DAJC-7F37045-2022	合格	2022-12-26	/
DAJC-7F37046-2022	合格	2022-12-27	/
DAJC-7F37047-2022	合格	2022-12-28	/
DAJC-7F381207-2022	合格	2022-11-8	/
DAJC-7F381208~1209-2022	合格	2022-11-9	/
DAJC-7F381210~1211-2022	合格	2022-11-10	/




报告编号	结论	报告日期	影像资料
DAJC-7F381212-2022	合格	2022-11-11	/
DAJC-7F381234~1235-2022	合格	2022-11-15	
DAJC-7F381236~1237-2022	合格	2022-11-16	





报告编号	结论	报告日期	影像资料
DAJC-7F381238~1239-2022	合格	2022-11-17	
DAJC-7F381240-2022	合格	2022-11-17	
DAJC-7F381245-2022	合格	2022-11-17	


报告编号	结论	报告日期	影像资料
DAJC-7F381246~1248-2022	合格	2022-11-18	
DAJC-7F381249~1251-2022	合格	2022-11-19	
DAJC-7F381252~1254-2022	合格	2022-11-20	
DAJC-7F381255~1256-2022	合格	2022-11-21	




报告编号	结论	报告日期	影像资料
DAJC-7F381257~1258-2022	合格	2022-11-22	
DAJC-7F381259~1260-2022	合格	2022-11-23	
DAJC-7F381261-2022	合格	2022-11-24	
DAJC-7F381265-2022	合格	2022-11-24	



报告编号	结论	报告日期	影像资料
DAJC-7F381266-2022	合格	2022-11-23	
DAJC-7F381267-2022	合格	2022-11-24	
DAJC-7F381268-2022	合格	2022-11-25	
DAJC-7F381269-2022	合格	2022-11-26	



报告编号	结论	报告日期	影像资料
DAJC-7F381270~1271-2022	合格	2022-11-26	
DAJC-7F381281~1282-2022	合格	2022-11-27	
DAJC-7F381283-2022	合格	2022-11-28	


报告编号	结论	报告日期	影像资料
DAJC-7F381284-2022	合格	2022-11-29	
DAJC-7F381285-2022	合格	2022-11-28	
DAJC-7F381286-2022	合格	2022-11-29	
DAJC-7F381287~1288-2022	合格	2022-11-30	




报告编号	结论	报告日期	影像资料
DAJC-7F381289~1290-2022	合格	2022-12-1	
DAJC-7F381291-2022	合格	2022-12-2	
DAJC-7F381292-2022	合格	2022-12-3	
DAJC-7F381293-2022	合格	2022-12-4	


报告编号	结论	报告日期	影像资料
DAJC-7F381294-2022	合格	2022-12-5	
DAJC-7F381295-2022	合格	2022-12-6	
DAJC-7F381296-2022	合格	2022-12-7	
DAJC-7F381297-2022	合格	2022-12-8	



报告编号	结论	报告日期	影像资料
DAJC-7F381298-2022	合格	2022-11-30	
DAJC-7F381299-2022	合格	2022-12-3	
DAJC-7F381302-2022	合格	2022-12-3	
DAJC-7F381303~1304-2022	合格	2022-12-4	
DAJC-7F381305-2022	合格	2022-12-5	



报告编号	结论	报告日期	影像资料
DAJC-7F381306-2022	合格	2022-12-5	
DAJC-7F381307~1308-2022	合格	2022-12-6	
DAJC-7F381309-2022	合格	2022-12-7	
DAJC-7F381313~1314-2022	合格	2022-12-8	



报告编号	结论	报告日期	影像资料
DAJC-7F381315~1316-2022	合格	2022-12-9	
DAJC-7F381317-2022	合格	2022-12-9	




报告编号	结论	报告日期	影像资料
DAJC-7F381318~1319-2022	合格	2022-12-10	
DAJC-7F381320~1321-2022	合格	2022-12-11	
DAJC-7F381322-2022	合格	2022-12-12	

报告编号	结论	报告日期	影像资料
DAJC-7F381325~1326-2022	合格	2022-12-12	
DAJC-7F381327~1329-2022	合格	2022-12-13	
DAJC-7F381334-2022	合格	2022-12-17	

报告编号	结论	报告日期	影像资料
DAJC-7F381335~1336-2022	合格	2022-12-17	
DAJC-7F381337~1339-2022	合格	2022-12-18	
DAJC-7F381340~1341-2022	合格	2022-12-18	
DAJC-7F381342-2022	合格	2022-12-19	

报告编号	结论	报告日期	影像资料
DAJC-7F381343-2022	合格	2022-12-20	
DAJC-7F381344-2022	合格	2022-12-21	
DAJC-7F381345-2022	合格	2022-12-22	
DAJC-7F381352-2022	合格	2022-12-23	
DAJC-7F381353~1354-2022	合格	2022-12-29	

报告编号	结论	报告日期	影像资料
DAJC-7F381355-2022	合格	2022-12-23	
DAJC-7F381356~1357-2022	合格	2022-12-24	
DAJC-7F381358-2022	合格	2022-12-25	
DAJC-7F381359-2022	合格	2022-12-25	
DAJC-7F381360~1361-2022	合格	2022-12-26	

报告编号	结论	报告日期	影像资料
DAJC-7F381362~1363-2022	合格	2022-12-27	
DAJC-7F381366-2022	合格	2023-12-28	
DAJC-7F381367-2022	合格	2022-12-29	
DAJC-7F381368-2022	合格	2022-12-30	

报告编号	结论	报告日期	影像资料
DAJC-7F381369~1370-2022	合格	2022-12-31	
DAJC-7F46207~210-2022	合格	2022-12-10	
DAJC-7F46219~220-2022	合格	2022-12-17	

报告编号	结论	报告日期	影像资料
DAJC-7F47361-2022	合格	2022-11-6	
DAJC-7F47362~367-2022	合格	2022-11-13	

报告编号	结论	报告日期	影像资料
DAJC-7F47368-2022	合格	2022-11-14	
DAJC-7F47438~442-2022	合格	2022-12-4	

报告编号	结论	报告日期	影像资料
DAJC-7F47448~449-2022	合格	2022-12-10	
DAJC-7F47450~453-2022	合格	2022-12-15	

报告编号	结论	报告日期	影像资料
DAJC-7F47454~456-2022	合格	2022-12-22	
DAJC-7F83017-2022	合格	2022-9-30	/
DAJC-7F143934~3965-2022	合格	2022-12-9	

报告编号	结论	报告日期	影像资料
DAJC-7F143968~3985-2022	合格	2022-12-13	
DAJC-7F151196~1197-2022	合格	2022-12-13	

报告编号	结论	报告日期	影像资料
DAJC-7F161258~1261-2022	合格	2022-12-13	
DAJC-7F23320-2022	所检试件合格	2022-12-27	/
DAJC-7F75188-2022	合格	2022-12-12	 

报告编号	结论	报告日期	影像资料
DAJC-7F75189-2022	合格	2022-12-15	
DAJC-7F75190~198-2022	合格	2022-12-12	
DAJC-7F75199-2022	合格	2022-12-15	

报告编号	结论	报告日期	影像资料
DAJC-7F75200~202-2022	合格	2022-12-12	
DAJC-7F75203~209-2022	合格	2022-12-15	
DAJC-7F75210~225-2022	合格	2022-12-12	

报告编号	结论	报告日期	影像资料
DAJC-7F75226-2022	合格	2022-12-15	